

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 7/22/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S02SS1008MH

Test ID: D1032-031003

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Manhole	S02UU1009MH
0			Start of Survey	
0			Dye Test Visible	@ Tap - toilet
0			Water Level	
0			Dye Test Visible	@ Tap - downspout
1			General Observation	DOWN SPOUT CAN RUN INTO BROKEN
1.10000024			End of Survey	DYE TEST COMPLETED
1.10000024			Manhole	S02SS1008MH